

DEPARTMENT OF NATURAL RESOURCES DIVISION OF OIL, GAS AND MINING



INSPECTION REPORT

1594 West North Temple, Suite 1210 PO Box 145801

Salt Lake City, Utah 84114-5801 Michael O. Leavitt

Governor

Lowell P. Braxton Division Director

801-538-5340 801-359-3940 (Fax) 801-538-7223 (TDD)

Partial: XXX Complete: Exploration: Inspection Date & Time: 9/14/99 / 9:15a.m.-12:30p.m. Date of Last Inspection: 8/10/99

| Mine Name: <u>Dugout Canyon</u> County: <u>Carbon</u> Permit Number: <u>ACT/007/039</u> | | | | | | |
|---|--|--|--|--|--|--|
| Permittee and/or Operator's Name: Canyon Fuel Company | | | | | | |
| Business Address: P.O. Box 1029, Wellington, Utah 84542 | | | | | | |
| Type of Mining Activity: Underground XXX Surface Prep. Plant Other | | | | | | |
| Company Official(s): Ken Payne, Chris Hansen | | | | | | |
| State Officials(s): Steve Demczak Federal Official(s): None | | | | | | |
| Weather Conditions: Warm, 70's | | | | | | |
| Existing Acreage: Permitted-4035 Disturbed-20.1 Regraded- Seeded- Bonded- | | | | | | |
| Increased/Decreased: Permitted Disturbed Regraded Seeded Bonded | | | | | | |
| Status:Exploration/_XXX_Active/_ Inactive/_ Temporary Cessation/_ Bond Forfeiture | | | | | | |
| Reclamation (_Phase I/_Phase II/_Final Bond Release/_LiabilityYear) | | | | | | |
| | | | | | | |

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

Instructions

- Substantiate the elements on this inspection by checking the appropriate performance standard.
 - For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
 - For <u>partial inspections</u> check only the elements evaluated.
- Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
- Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
- Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

| | | EVALUATED | N/A | COMMENTS | NOV/ENF |
|-----|--|-------------------|-------------------|-------------------|-------------------|
| 1. | PERMITS, CHANGE, TRANSFER, RENEWAL, SALE | [XX] | [] | [XX] | [] |
| 2. | SIGNS AND MARKERS | <u>ixxi</u> | Ħ | [XX] | Ħ |
| 3. | TOPSOIL | [] | Ħ | [] | Ħ |
| 4. | HYDROLOGIC BALANCE: | | | | |
| a. | DIVERSIONS | [XX] | [] | [XX] | [] |
| b. | SEDIMENT PONDS AND IMPOUNDMENTS | [XX] | Ħ | [XX] | Ħ |
| c. | OTHER SEDIMENT CONTROL MEASURES | [] | Ħ | [] | Ħ |
| d. | WATER MONITORING | Ħ | Ϊī | Ħ | 11 |
| e. | EFFLUENT LIMITATIONS | Ħ | Ħ | ii ii | Ti . |
| 5. | EXPLOSIVES | Ħ | П | Ti . | Ħ |
| 6. | DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES | Ħ | i i | īi | Ħ |
| 7. | COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS | \overline{XX} | П | $\overline{[XX]}$ | Ħ |
| 8. | NONCOAL WASTE | XXI | Π | XX | - 11 |
| 9. | PROTECTION OF FISH, WILDLIFE AND | | _ | | - |
| | RELATED ENVIRONMENTAL VALUES | f 1 | [] | [] | [] |
| 10. | SLIDES AND OTHER DAMAGE | ក | П | īī | īī |
| 11. | CONTEMPORANEOUS RECLAMATION | | П | īī | Π |
| 12. | BACKFILLING AND GRADING | i i | П | Ī | ī |
| 13. | REVEGETATION | $\overline{[XX]}$ | П | [_] [XX] | īī |
| 14. | SUBSIDENCE CONTROL | 1 | | | \Box |
| 15. | CESSATION OF OPERATIONS | | $\overline{\Box}$ | | \Box |
| 16. | ROADS: | _ | _ | , | _ |
| a. | CONSTRUCTION/MAINTENANCE/SURFACING | \Box | Ш | \Box | П |
| b. | DRAINAGE CONTROLS | Ī | | $\overline{\Box}$ | $\overline{\Box}$ |
| 17. | OTHER TRANSPORTATION FACILITIES | | 口 | | \Box |
| 18. | SUPPORT FACILITIES/UTILITY INSTALLATIONS | $\overline{[XX]}$ | | $\overline{[XX]}$ | \Box |
| 19. | AVS CHECK (4th Quarter-April, May, June)(date) | | Π | | Ī |
| 20. | AIR QUALITY PERMIT | | Πī | \Box | |
| 21. | BONDING & INSURANCE | īī | īī | īī | Πī |

INSPECTION REPORT

(Continuation sheet)

Page <u>2</u> of <u>2</u>

PERMIT NUMBER: ACT/007/039

DATE OF INSPECTION: 9/14/99

(Comments are Numbered to Correspond with Topics Listed Above)

1. PERMIT-

The permittee will be submitting several amendments dealing with hydrology and updating the surface facility map. The surface facility map was field-checked in August prior to submittal.

2. SIGNS AND MARKERS -

Identification signs meet the requirements of the R645 Coal Rules. The perimeter markers were spotchecked and are located around the perimeter of the disturbed areas. The permittee will be marking and adding several more perimeter markers.

4A. DIVERSIONS -

The diversions were spot-checked and presently comply with the Coal Rules, but maintenance is needed in several areas due to sediment build up.

4B. SEDIMENT PONDS -

The sediment pond has contained water but was not discharging during the inspection. Permittee plans to do additional work to the inlets and outlets of the sediment pond and will be submitting an amendment.

7. REFUSE -

There was no refuse being stacked or stored at Dugout mine.

8. NON-COAL WASTE -

The area was clear of non-coal waste material.

13. **REVEGETATION** -

The permittee plans to revegetate the cut slope and sediment pond embankments this fall.

18. SUPPORT FACILITIES -

The office and warehouse building is scheduled for construction this fall. Some of the other surface facilities are completed and others are nearly completed.

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas, and Mining.

Copy of this Report:

Mailed to: <u>Chris Hansen (Canyon Fuel)</u> Given to: <u>Pam Grubaugh-Littig (DOGM)</u>

Henry Austin (OSM)

Filed to: Price Field Office

Date: September 15, 1999

Inspector's Signature:

1 (X bull